

# NRC Publications Archive Archives des publications du CNRC

## Errors in concrete structures

Allen, D. E.

This publication could be one of several versions: author's original, accepted manuscript or the publisher's version. / La version de cette publication peut être l'une des suivantes : la version prépublication de l'auteur, la version acceptée du manuscrit ou la version de l'éditeur.

## Publisher's version / Version de l'éditeur:

Canadian Journal of Civil Engineering, 6, 3, pp. 465-467, 1979-09

### NRC Publications Record / Notice d'Archives des publications de CNRC:

https://nrc-publications.canada.ca/eng/view/object/?id=05938b5b-e985-404a-b44d-c1f4986d7667 https://publications-cnrc.canada.ca/fra/voir/objet/?id=05938b5b-e985-404a-b44d-c1f4986d7667

Access and use of this website and the material on it are subject to the Terms and Conditions set forth at <u>https://nrc-publications.canada.ca/eng/copyright</u> READ THESE TERMS AND CONDITIONS CAREFULLY BEFORE USING THIS WEBSITE.

L'accès à ce site Web et l'utilisation de son contenu sont assujettis aux conditions présentées dans le site https://publications-cnrc.canada.ca/fra/droits LISEZ CES CONDITIONS ATTENTIVEMENT AVANT D'UTILISER CE SITE WEB.

**Questions?** Contact the NRC Publications Archive team at PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca. If you wish to email the authors directly, please see the first page of the publication for their contact information.

**Vous avez des questions?** Nous pouvons vous aider. Pour communiquer directement avec un auteur, consultez la première page de la revue dans laquelle son article a été publié afin de trouver ses coordonnées. Si vous n'arrivez pas à les repérer, communiquez avec nous à PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca.





er H**1** W21d

5.853

B.D.

National Research Council Canada Conseil national de recherches Canada

ANALYZED

## ERRORS IN CONCRETE STRUCTURES

by D. E. Allen

Reprinted from Canadian Journal of Civil Engineering Vol. 6, No. 3, September 1979 pp. 465–467

DBR Paper No. 853 Division of Building Research 7404

This publication is being distributed by the Division of Building Research of the National Research Council of Canada. It should not be reproduced in whole or in part without permission of the original publisher. The Division would be glad to be of assistance in obtaining such permission.

Publications of the Division may be obtained by mailing the appropriate remittance (a Bank, Express, or Post Office Money Order, or a cheque, made payable to the Receiver General of Canada, credit NRC) to the National Research Council of Canada, Ottawa. K1A 0R6. Stamps are not acceptable.

A list of all publications of the Division is available and may be obtained from the Publications Section, Division of Building Research, National Research Council of Canada, Ottawa. K1A 0R6.



#### NOTES

### **Errors in concrete structures**

D. E. Allen

Structures Section, Division of Building Research, National Research Council of Canada, Ottawa, Ont., Canada KIA 0R6

Received February 19, 1979

Accepted March 20, 1979

One hundred and eighty-eight cases of error in concrete structures, 29 of which resulted in collapse and 118 in distress, deterioration, excessive cracking, spalling, deflection, or settlement, were collected from consulting engineers and government departments across Canada. The survey indicated that about half the errors originated in the design and the other half were due to faulty construction. Most of the collapses occurred during construction, mainly as a result of inadequate formwork or temporary bracing; some were due to detailing errors in design. Most serviceability failures, on the other hand, occurred during use. Many of those failures were due to lack of consideration in design of deflection or of the effects of temperature, shrinkage, and creep.

Can. J. Civ. Eng., 6, 465-467 (1979)

#### Survey

A survey of errors that led to or could have led to failure of concrete structures was carried out by sending a questionnaire to design engineers and inspection agencies across Canada. The survey was undertaken as part of a larger one across North America organized by Committee 348 of the American Concrete Institute (ACI) in an attempt to "develop a profile of the practices, activities and circumstances making up the design and construction of concrete structures that tend to lead toerrors." Details of the questionnaire are given in Allen (1977). Anonymity of names and places concerning each case was assured as this information was not requested.

In Canada the questionnaire was sent to approximately 250 consulting engineering firms, to all federal and provincial government departments of highways, public works, and agriculture, and to building departments of municipalities with a population of more than 100 000. The responses from various sources are given in Table 1. The 188 cases reported were obtained from about 50 sources ranging from 1 to 22 cases each.

The responses varied from detailed and illumi-

TABLE 1. Responses

Consulting engineers (a few from testing labs)	142
Municipal building departments	13
Provincial highway departments	16
Government public works and hydro departments	12
Government agricultural departments	5
Total	188

nating to vague and occasionally ambiguous. To a considerable extent this was due to the lack of clarity in the questionnaire (Allen 1977). For example, "distress" was not clearly defined and in analyzing the results was interpreted as a structural condition that indicated insufficient safety against collapse, not just unserviceability. Despite this shortcoming, a summary of the results will be of interest to designers and builders. A more detailed analysis of the results of the ACI error survey is given in Fraczek (1979).

#### **Discussion of Results**

Tables 2 and 3 provide a breakdown of errors reported according to type of construction and component. Because of the fairly broad coverage indicated in Tables 1, 2, and 3, the cases provide a sample that is fairly representative of the total population of failures of engineered concrete structures in Canada, except for those caused by deterioration that occur after many years and may not be considered as structural failures. The cases do not provide a representative sample of the total

TABLE 2. T	pe of	construction
------------	-------	--------------

Posttensioned concrete	16
Composite construction	6
Plain concrete	2
Concrete block	7
Precast construction	
Reinforced concrete	8
Prestressed concrete	14

0315-1468/79/030465-03\$01.00/0

©1979 National Research Council of Canada/Conseil national de recherches du Canada

TABLE 3. Component affected

Slab	41
Bridge deck	10
Beam	23
Column	10
Pile or pier	16
Wall	8
Retaining, tank, or basement wall	25
Foundation	13
Connection	28
Formwork, temporary bracing or fastening	12

TABLE 4. Types of errors

	No. of cases
Design-total	103
Loading (including temperature and shrinkage)	22
Analysis and design	60
Detailing	25
Construction-total	92
Formwork, bracing, supports	27
Installation of reinforcing	31
Concreting	21
Overloading or impact	8
Contractor's interpretation of working drawing	s 10
Use—overloading	1

population of errors because most errors caught in time were not reported.

Table 4 gives a breakdown of the types of errors reported. Approximately half were design errors and half were construction errors. Most design errors were classified as "analysis and (or) design" or "calculation" in the questionnaire but a number of these were probably "detailing" errors, i.e., inadequate consideration of connections, anchorages, and reinforcing details. A number of detailing errors, some of which led to collapse, were caused by a lack of consideration of the effects of temperature or shrinkage or of eccentric forces.

Table 5 gives a more detailed breakdown of those errors that resulted in failure. Most collapses occurred during construction, primarily due to formwork failure or inadequate temporary bracing. A number of collapses occurred because of detailing error in design. Of the six collapses that occurred during use, two were due to detailing error and two to not considering lateral load. Most serviceability failures, i.e., excessive cracking and deflection, occurred during use and originated primarily in the design. Deflection problems most often arose because of inadequate consideration of deflection or of the effects of deflection. Only seven cases of deterioration were reported, which is certainly not representative of how widespread it is in practice.

More detailed descriptions of the errors given in the responses are contained in Table 6. These are self-explanatory and are worth studying to understand the kinds of troubles that arise in concrete structures in Canada. Table 6 indicates that most design errors resulting in structural failure (including failure of temporary supports), other than those due to deterioration, were due to a miscinception or forgetting of the general behaviour of the structure as a whole, or of its members, connections, or details, and of the kinds of forces that will occur. Relatively few were due to an inaccurate assessment of the magnitudes of forces or resistances that occurred or of the safety factor required. Table 6 indicates that contruction errors other than design of temporary supports consisted primarily of incorrect procedure, for example, omissions, misplacement, wrong materials or products, incorrect curing.

	Failure	e occurred durin	g	Due to errors in			
		Use Construction	Design		Construction		Use
	Use		Detailing	Other	Formwork bracing etc.	Other	
Ultimate limit states							
Collapse	6	23	6	6	13	6	
Distress	32	26	12	19	7	25	1
Serviceability limit states							
Cracking, spalling	17	8	6	12	1	7	
Deflection, settlement	17	11	1	16	1	11	
Clearance, gaps, holes	2	1		2	1		
Deterioration	6	1		3		4	
Tota	1 80	70	25	58	23	53	1

TABLE 5. Breakdown of cases where failure occurred

TABLE 6. Descriptions of errors

-				
	Error description	No. of cases	Error description	No. of cases
1.	Design		Posttensioning anchor stirrups left out	2
	Detailing error—collapse	7	Concrete insufficiently strong during	
	Lateral loading not properly considered	8	posttensioning	1
	Lateral support not properly considered	3 X	Unbalanced construction loads-wharf	
	Neglect of temperature shrinkage or	5	caisson cracked	1
	creep effects	10	Sliding bearing concreted in	î
	Inadequate soil investigation	10	Wooden negs left in concrete leakage in	•
	Hydrostatic unlift or soil evalling	2	waffle slab	
	Neglect of deflection effects	2	Mud in pier shaft	1
	Plain concrete or black with a bird to	8	Wall form 1/2 mensional thickness	1
	Plain concrete or block walls subject to		wall form 1/3 required thickness	1
	earth pressure	4	Block wall form not braced against concre	te
	Concrete specification (no air entrainment,		pressure	1
	sulphate attack)	2	Old concrete surface not cleaned—crack du	le
	Leakage protection	1	to bond failure	1
	Overlooked weight of masonry wall	1	Reinforcing placed upside down	1
	Avalanche forces greater than predicted	1	Overexcavation of ground intended to resis	st
	Lack of overflow device-hydrostatic tank		sliding	1
	pressure	1	Frost penetration below footing reduced	
	Neglected radial temperature movements in	-	soil strength	1
	curved bridge (cracked pier)	1	Contractor substituted bearing materials-	
	Neglected tension across tapered nier	1	corrosion	1
	Skew reinforcingcorner cracking of	1	Flying forms not anchored_flew off	1
	bridge deck	1	Indequate temporary factoring of presset	1
	No inside reinforcing in culic drivel show	1	madequate temporary fastening of precast	
	wall leakage		paner Ne spectrus beseine between beseinder	1
	Facentrie les dins au les telles	1	No erection bracing between box girders	1
	Neuric loading neglected by precaster	1	Protection against ice formation in holes	1
	No stirrups	1	3 Other	
	Sharp curves in prestress splice detail-		Overloading during use	4
	cracking	1	Soil grasion due to watermain look	1
4	Unstable hangar supports for T beams	1	Son crosion due to watermain leak	e <b>t</b> e
	Detailing-bar congestion	1		
	Panels bowed out at corner of building—		Advandedgement	
	leakage	1	Acknowleugement	
	Insufficient bridge clearance	1	The author would like to thank the mo	ore than 50
	Detailing to avoid effects of ice formation	1	man and ants for marriding valuable infor	motion on
2 6	Construction		respondents for providing valuable info	mation on
2. 1	Formularly failure colleges		errors in concrete structures, and for their	comments
	There is a second but the second but	6	about the questionnaire. This note is a c	ontribution
	Thawing of ground below mudsilis—collaps	e 2	from the Division of Building Research	National
	Inadequate temporary bracing—collapse	5	Tom the Division of Building Research	1, 1 attoliat
	Overloading during construction	6	Research Council of Canada, and is pub	lisned with
	Impact during construction	5	the approval of the Director of the Divis	ion.
	Concrete mix	6		
	Frozen concrete	2	ALLEN D E 1077 ACLETTOR SURVEY Considion	data Division
	Inadequate chair supports for reinforcing	3	of Building Desearch, National Desearch Court	all of Canada
	Wrong steel	2	Other Other Dubling Research, National Research Coun	ch of Callada,
			Uuawa, Unt., Building Research Note No. 123.	

7

Settlement or sliding due to improper construction methods

FRACZEK, J. 1979. AC1 error survey. Concrete International. (To be published.)

 TABLE 6 (Concluded)