

NRC Publications Archive Archives des publications du CNRC

NRC PERD 079 Project - Task 1 - Findings from the Carmacks Yukon survey

Rousseau, M. Z.; Manning, M. M.; Said, M. N.; Swinton, M. C.; Cornick, S. M.

NRC Publications Archive Record / Notice des Archives des publications du CNRC :

<https://nrc-publications.canada.ca/eng/view/object/?id=13d2d11e-16b3-4e1b-ae3a-d11989e94723>

<https://publications-cnrc.canada.ca/fra/voir/objet/?id=13d2d11e-16b3-4e1b-ae3a-d11989e94723>

Access and use of this website and the material on it are subject to the Terms and Conditions set forth at

<https://nrc-publications.canada.ca/eng/copyright>

READ THESE TERMS AND CONDITIONS CAREFULLY BEFORE USING THIS WEBSITE.

L'accès à ce site Web et l'utilisation de son contenu sont assujettis aux conditions présentées dans le site

<https://publications-cnrc.canada.ca/fra/droits>

LISEZ CES CONDITIONS ATTENTIVEMENT AVANT D'UTILISER CE SITE WEB.

Questions? Contact the NRC Publications Archive team at

PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca. If you wish to email the authors directly, please see the first page of the publication for their contact information.

Vous avez des questions? Nous pouvons vous aider. Pour communiquer directement avec un auteur, consultez la première page de la revue dans laquelle son article a été publié afin de trouver ses coordonnées. Si vous n'arrivez pas à les repérer, communiquez avec nous à PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca.



NRC PERD 079 Project- Task 1

**Findings from the Carmacks Yukon Survey
prepared by
Madeleine Rousseau, Marianne Manning,
Nady Said, Mike Swinton and Steve Cornick
Feb. 2007**



National Research
Council Canada

Conseil national
de recherches Canada

Canada

Carmacks Survey

- In March 2005 The Sheltair Group in Vancouver was contracted out to do the field survey in Yukon
- Yukon Housing Corporation provided support in finding the houses; Carmacks First Nations community was selected
- 8 houses/region
 - 4 with reported moisture troubles
 - 4 without reported moisture troubles
 - Carmacks survey was carried out from January 19 to February 21, 2006

Data Collection

- Hobo RH and T sensors
 - calibrated at IRC (up to about 60% RH)
 - 2 indoors per house
 - On wall of room with high moisture source or with identified moisture problem
 - One out of 16 indoor sensors did not work
 - one outdoors per survey region
 - Set to capture data every three minutes
- EnerGuide for Houses survey, fan depressurization test and Hot 2000 analysis
- IRC-made questionnaire on basic building characteristics

House Characteristics

- Manually-operated exhaust fans in kitchen and/or bathroom
- Moisture problems:
 - Mould growth on exterior walls, behind furniture, at wall-floor and wall-ceiling junctions, at window sills
 - Frost on glazing
- Two non-moisture troubled houses experienced mould growth as well but occupants regularly wash the walls to remove mould growth
- Several household have/plan to remove the drywall and replace it with wood panelling
- 8 single detached houses (1 is a mobile home)
- Wood-frame 2X6
- 6 houses built 10 years ago or less
- Very leaky (between 5-19 ACH @ 50 Pa)
- 2 houses built in 1975 and 1978
- Occupancy varied between 1 to 6 persons
- Double glazed PVC windows
- 7 houses are heated with a wood-stove & no heat distribution system
- MT households have fewer or zero occupants during the day

House Characteristics

House	ACH @ 50 Pa	EGH rating (Age of construction)	Min and Max indoor RH recorded	Occupancy load (day/night)
MT- #1	7.8	49 (1978)	7-52%	6 occupants (0/6)
MT #2	19.0	34 (1975)	7-98 %	1 occupant (1/1)
MT #5	8.9	57 (2002)	10-67 %	5 occupants (0/5)
MT #6	12.0	61 (2002)	9-79 %	4 occupants (0/4)
NMT #3	9.6	57 (2002)	13-92 %	3 occupants (2/3)
NMT #4	13.6	57 (1996)	4-91 %	2 occupants (0/2)
NMT #7	7.9	61 (2002)	17-60 %	2 occupants (1/1)
NMT #8 (mobile home)	5.0	70 (1998)	20-66 %	6 occupants (5/6)

Characteristics of Non moisture troubled Sample

Non-Moisture Troubled Sample										
House No.	Hobo sensors & location	No. of occupants (day/night)	Windows	Humidifier	House-general	Heating system	Ventilation	EGH rating / ACH @50 Pa/ELA (cm ²)	Problems	Comments
3 (250)	839964: bedroom closet 839971: kitchen	3 (2/3)	Double glazed PVC, fixed and casement Curtains closed during visit Plastic in place to reduce draughts	Drying of clothes indoors	Built 2002 807 sq ft Bungalow	Wood stove. No heat distribution	Manually-operated exhaust fan in bathroom	57/9.6/178cm ²		
4 (251)	839977: kitchen 839975: bedroom closet	2 (0/2)	Double glazed PVC, fixed and sliders Curtains closed during visit		Built 1996 851 sq ft	Wood stove. No heat distribution	Manually-operated exhaust fan in bathroom	57/13.6/184 cm ²		
7 (254)	839979:kitchen 839973: living room	2 (1/1)	Double glazed PVC, fixed and sliders Curtains open during visit	Pot on stove	Built 2002 860sq ft Bungalow	Wood stove. No heat distribution	Manually-operated exhaust fans in kitchen and bathroom	61/7.9/166cm ²	No moulds observed. Occupant cleans walls bi-weekly to control mould growth	
8 (255)	839982: kitchen 839967: living room	6 (5/6)	Double glazed PVC, fixed and sliders Curtains open during visit		Built 1998 863 sq ft Mobile home	Oil furnace with forced air system	Manually-operated exhaust fans in kitchen and bathroom	70/5.0/64 cm ²	Occupant cleans walls bi-weekly to control mould growth	Interior finish is wood panels

Characteristics of Moisture trouble Sample

Moisture-Troubled Sample										
House No.	Hobo sensors & location	No. of occupants (day/night)	Windows	Source of humidification	House-general	Heating system	Ventilation	EGH rating / ACH @50 Pa/ELA (cm ²)	Problems	Comments
1 (248)	839968:bedroom 839980: hall in storage cupboard	6 (0/6)	Double glazed PVC, fixed and sliders Curtains open during visit	No	Built 1978; 1517 sq ft, Bungalow	Wood stove is stocked AM and evening only; no heat distribution	Manually-operated exhaust fans in kitchen and bathroom	49/7.8/220 cm ²	*Frost on glass and frame *Mould on ext. walls, bathroom, behind furniture *Water damage under window sill and on bathroom ceiling	Drywall is replaced with wood panelling
2 (249)	839965: bathroom 839981: living room	1 (1/1)	Double glazed PVC, fixed and casement Curtains closed during visit	Pot of water boils all day Dryer is vented into bathroom	Built 1975 1052 sq ft Bungalow	Wood stove No heat distribution	Manually-operated exhaust fans in kitchen and bathroom	34/19/308 cm ²	*Frost on glass and frame *Mould on ext. walls, bathroom, behind furniture	Some drywall was removed. Plans are to replace it with wood panelling
5 (252)	839972: kitchen (above stove?) 839966:living room	5 (0/5)	Double glazed PVC, fixed and sliders Curtains close during visit	Exposed earth in crawl space Fresh air intake for stove in crawl space	Built 2002 902sq ft Bungalow	Wood stove No heat distribution	Manually-operated exhaust fans in kitchen and bathroom	57/8.9/188cm ²	Mould and frost on windows, in corners at floor and ceiling and on interior finish below window sill	Plans are to replace drywall with wood panelling
6 (253)	839976: kitchen 839978: hall	4 (0/4)	Double glazed PVC, fixed and sliders Curtains open during visit	Pot on stove	Built 2002 694 sq ft Log home	Wood stove No heat distribution	Manually-operated exhaust fans in kitchen and bathroom	61/12/178 cm ²	Mould and frost on windows	Occupant cleans walls bi-weekly to control mould growth

Moisture Troubled (MT) Houses



**248(#1)MT
EGH: 49**



**249 (#2) MT
EGH: 34**



**253 (#6) MT
EGH: 61**



**252 (#5) MT
EGH:57**

Non Moisture Troubled (NMT) Houses



251 (#4) NMT
EGH: 57



250 (#3) NMT
EGH: 57



254 (#7) NMT
EGH: 61



255 (#8) NMT
EGH: 70

Types of Moisture Troubles



Mould growth in exterior walls, particularly behind furniture and at lower portion of floor. Mould noted in bathroom



Windows have frost on them and are frozen open



Stained drywall removed at time of site visit. It was noted that the air barrier was incomplete around penetrations. There was approximately 1cm thick of ice on the inside face of the exterior sheathing at these locations



Mould on walls, at corners of floor and ceilings



Sensor Locations



839968 (#1a)
Bedroom close to exterior wall



839980 (#1b)
in hall in storage cupboard



839981 (#2b)
Living room



839965 (#2a)
Bathroom

Sensor Locations



839971 (#3b)
Kitchen



839964 (#3a)
Bedroom closet



839977 (#4b)
Kitchen



839975 (#4a)
Bedroom closet

Sensor Locations



839972 (#5b)
Kitchen (above stove or fridge?)



839966 (#5a)
Living room



839972 (#6a)
Kitchen



839978 (#6b)
Hall in open closet

Sensor Locations



839979 (#7a)
Kitchen



839982 (#8a)
Kitchen



839967 (#8b)
Living room

Data Analysis

- Average outdoor RH and T in Carmacks during the survey period
- Average daily Temperature in NMT and MT relative to outdoors
- Average indoor RH in NMT and MT relative to outdoor and type of room
- Characteristics and duration of high humidity events


Very cold: T_{ext} rarely above 0C

Average outdoor T for the survey period: -18C

Min T_{ext} reached -40C

Exterior Average Daily Temperature

Exterior - Daily Temperature




- House 5 is warmer (28-31C) (kitchen-LR)
- House 1 is cooler (10-20C) (storage shelf- Closed off?)

Carmacks

Average Daily Temperature Moisture Troubled Houses

Average Daily Temperature - Moisture-Troubled Houses




•House 4B (kitchen) was cool (followed outdoor T)

House 7A (kitchen) ran warmer
Carmacks

Temperature

Non Moisture Troubled Houses

Average Daily Temperature - Non Moisture-Troubled Houses




Large Daily Fluctuations of Temperature

Carmacks


2b - Daily Temperature

House 2 - MT - 1 occupant (1 day/1 night) - 19 ACH@50Pa



24-hour indoor T and RH fluctuations for 2B sensor

Temperature and Humidity - 2b Living room



No one at home during the day (?)


Wood stove operation

High Indoor Temperature

Carmacks

5b - Daily Temperature Kitchen

House 5 - MT - 5 occupants (0 day/5 night) - 9.6 ACH@50Pa




Only household with a oil furnace
with forced air heat distribution,
more airtight & several occupants
during the day

Narrower band of Daily Temperature Fluctuations

Carmacks


8b - Daily Temperature

House 8 - NMT - 6 occupants (5 day/6 night) - 5.0 ACH@50Pa



- Daily averages of Indoor RH data follow trends in outdoor RH
- House 3 (NMT) has highest daily average RH (kitchen and bedroom closet)
- House 2 (MT) has lowest daily average RH (bathroom and LR) BUT...

Daily Average Relative Humidity in All Houses




The case of House 2 (MT)

1st: large Temp swings

Carmacks

2b - Daily Temperature

House 2 - MT - 1 occupant (1 day/1 night) - 19 ACH@50Pa



The case of House 2 (MT)


2nd: large RH swings

Carmacks

2a - Daily Relative Humidity

Bathroom

House 2 - MT - 1 occupant (1 day/1 night) - 19 ACH@50Pa



The case of House 2 (MT)


large RH swings

Carmacks

2b - Daily Relative Humidity

Living Room

House 2 - MT - 1 occupant (1 day/1 night) - 19 ACH@50Pa




NRC - CMRC

MT Houses; RH swings

Carmacks

5b - Daily Relative Humidity Kitchen

House 5 - MT - 5 occupants (0 day/5 night) - 9.6 ACH@50Pa




MT Houses; RH swings

Carmacks

6a - Daily Relative Humidity Kitchen

House 6 - MT - 4 occupants (0 day/4 night) - 13.6 ACH@50Pa




House 8 is high occupancy BUT a mobile home (prefab), more airtight, more insulated, with oil furnace and forced air distribution

Indoor RH in Non Moisture Troubled Houses

Carmacks

Average Daily Relative Humidity - Non Moisture-Troubled Houses




House 8 (NMT): Narrower band of RH and Temp. fluctuations

8b= kitchen

Carmacks

8b - Daily Temperature


House 8 - NMT - 6 occupants (5 day/6 night) - 5.0 ACH@50Pa



Carmacks

8b - Daily Relative Humidity


House 8 - NMT - 6 occupants (5 day/6 night) - 5.0 ACH@50Pa



Time spent at High Humidity- Wet Rooms


Carmacks

Percentage of Time spent at High Humidity during 20-Jan-06 to 19-Feb-06
bathroom and kitchen sensors



Time Spent at High Humidity- Other Rooms

Percentage of Time spent at High Humidity during 20-Jan-06 to 19-Feb-06
house sensors (outside bathroom and kitchen)




Difference in Humidity Ratio (Exterior – Interior)

- Range of indoor moisture loads – from 5g/kg_{da} to 18 g_w/kg_{da}

- No obvious relationship to moisture problems

Carmacks

Maximum Difference in Humidity Ratio (Exterior - Interior)
20-Jan-06 to 19-Feb-06







Carmacks Yukon (Jan-Feb 2006)

- Cold monitoring month with ext. temperature down to -40C and rarely above 0C.
- Bldg envelopes were subjected to large daily average indoor temperature swings between max 37C and min 7C. Bldg envelopes act as condensing plates.
- Peaks 3 min. indoor temperature: as low as 10C and as high as 37C
- Heating system was typically central wood stove and no heat distribution system. House with oil furnace and forced air experienced more stable RH and T indoors.
- Bathroom and kitchen experienced an extra moisture load of 6 to 18 g_w/kg_{da} relative to outdoors
- Moisture troubles may have a link with absence of occupancy during the day. No one at home during the day means the house temperature drops down considerably (no manual feeding of the stove) and exterior wall surfaces are allowed to cold down.
- Solutions used included to wash wall surfaces regularly, put plastic on window glazing, change drywall for wood panelling.



Input for Experimental Studies

Scenarios	Indoor Conditions Outdoor Conditions	Comments
Constant RH and T		Max. monthly average measured indoors
Ramping RH levels, constant T		3 Levels: low, average, high e.g. 30%, 50%, 70%
Constant combined with short-lived peaks		Max. monthly average and extreme 20 minutes peaks (e.g. 90% RH)
Dynamic offset of moisture over outdoor absolute moisture level		Additional 1-3 grams water/kg of dry air into indoor air over outdoor level