NRC Publications Archive Archives des publications du CNRC

Thermal regulation manikin support frame Ryan, R.

For the publisher's version, please access the DOI link below./ Pour consulter la version de l'éditeur, utilisez le lien DOI ci-dessous.

Publisher's version / Version de l'éditeur:

https://doi.org/10.4224/8895750

Student Report (National Research Council of Canada. Institute for Ocean Technology); no. SR-2008-05, 2008-04

NRC Publications Archive Record / Notice des Archives des publications du CNRC : https://nrc-publications.canada.ca/eng/view/object/?id=34c6db9b-f85c-48ff-b666-93201c0f2c4f https://publications-cnrc.canada.ca/fra/voir/objet/?id=34c6db9b-f85c-48ff-b666-93201c0f2c4f

Access and use of this website and the material on it are subject to the Terms and Conditions set forth at https://nrc-publications.canada.ca/eng/copyright

READ THESE TERMS AND CONDITIONS CAREFULLY BEFORE USING THIS WEBSITE.

L'accès à ce site Web et l'utilisation de son contenu sont assujettis aux conditions présentées dans le site https://publications-cnrc.canada.ca/fra/droits

LISEZ CES CONDITIONS ATTENTIVEMENT AVANT D'UTILISER CE SITE WEB.

Questions? Contact the NRC Publications Archive team at

PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca. If you wish to email the authors directly, please see the first page of the publication for their contact information.

Vous avez des questions? Nous pouvons vous aider. Pour communiquer directement avec un auteur, consultez la première page de la revue dans laquelle son article a été publié afin de trouver ses coordonnées. Si vous n'arrivez pas à les repérer, communiquez avec nous à PublicationsArchive-ArchivesPublications@nrc-cnrc.gc.ca.








National Research Council Canada

Institute for Ocean Technology

Conseil national de recherches Canada

Institut des technologies océaniques





DOCUMENTATION PAGE

REPORT NUMBER	NRC REPORT NUMBER	DATE		
SR-2008-05		April 200	18	
REPORT SECURITY CLASSIFICATION		DISTRIBUTION		
UNCLASSIFIED		UNLIMITED		
TITLE				
	MANIKIN SUPPORT FRAME			
AUTHOR(S)				
Ron Ryan				
CORPORATE AUTHOR(S)/PER	FORMING AGENCY(S)			
IOT/NRC				
PUBLICATION				
N/A				
SPONSORING AGENCY(S)				
IOT/NRC				
IOT PROJECT NUMBER 42 2264 16		NRC FILE NUMBER		
KEY WORDS		PAGES	FIGS.	APPS.
Manikin, support frame		53	11	4
manikin while in an immer	design of a support frame to assist sion suit in water. The support fran s a human position while in an imn	ne will allov	v the manil	
Institute for (Arctic Avenu St. John's, N	search Council Ocean Technology le, P. O. Box 12093 IL A1B 3T5 772-5185, Fax: (709) 772-2462			

National Research Council Canada

Institute for Ocean Technology

Conseil national de recherches Canada

Institut des technologies océaniques

AUTOMATED IMAGE ANALYSIS FOR MARINE ICING EVENTS

SR-2008-04

Wayne Bruce

April 2008

Table of Contents

1.0	Introduction	1
2.0	Ice Accumulation	1
	2.1 Marine Icing Spray	2
3.0		
4.0		
	4.1 Positions	5
	4.2 Image Processing	7
	4.3 Edge Detection	
	4.4 Calibration	
	4.5 Sub-Pixels	10
	4.6 Generated Images	12
	4.7 Elliptical Structures	
5.0	· ·	
	5.1 Features	15
	5.2 Relationships	
6.0	·	
	Table of Figures	
Fiai		2
Fig:	ure 1: Icing event on the Kingfisher	2 3
Fig	ure 1: Icing event on the Kingfisherure 2: Splash occurred against the Kingfisher	3
Fig:	ure 1: Icing event on the Kingfisherure 2: Splash occurred against the Kingfisherure 3: MIMS cameras on the Caribou	3 4
Figi Figi	ure 1: Icing event on the Kingfisherure 2: Splash occurred against the Kingfisher	3 4 5
Figu Figu Figu	ure 1: Icing event on the Kingfisherure 2: Splash occurred against the Kingfisherure 3: MIMS cameras on the Caribouure 4: Icing and precipitation on MIMS cameraure 5: Positions used during automated analysis	3 5 7
Figu Figu Figu Figu	ure 1: Icing event on the Kingfisherure 2: Splash occurred against the Kingfisherure 3: MIMS cameras on the Caribouure 4: Icing and precipitation on MIMS cameraure 5: Positions used during automated analysisure 6: (a) Icing image rotated (b) rotated and converted to greyscale	3 5 7
Figu Figu Figu Figu Figu	ure 1: Icing event on the Kingfisherure 2: Splash occurred against the Kingfisherure 3: MIMS cameras on the Caribouure 4: Icing and precipitation on MIMS cameraure 5: Positions used during automated analysis	3 5 7 8
Figu Figu Figu Figu Figu Figu	ure 1: Icing event on the Kingfisher	3 5 8 9
Figo Figo Figo Figo Figo Figo Figo	ure 1: Icing event on the Kingfisher	3 5 7 8 9
Figu Figu Figu Figu Figu Figu Figu	ure 1: Icing event on the Kingfisher	358911

Appendices

Appendix A: Python Code for Automated Image Analysis
Appendix B: Sample Analysis Pictures for Icing Event (Dec. 29, 2006)
Appendix C: Icing Event Figures for Ice Accumulation

Automated Image Analysis for Marine Icing Events

1.0 Introduction

This report will focus on the analysis of ice accumulation using the Marine Icing Monitoring System (MIMS). Ice build-up continues to be a concern for offshore structures and vessels during the winter months. Python, a programming language, along with images from the MIMS technology uses an automated approach to calculate the rate and thickness of ice during icing events. Currently, the program investigates icing events occurring in the 2006/2007 winter on the Atlantic Kingfisher, an offshore supply vessel providing support for Petro-Canada's Terra Nova project. MIMS, developed by the Institute for Ocean Technology, continues to try and improve this technology and increase safety conditions during icing events.

2.0 Ice Accumulation

Ice accumulation on vessels can be a dangerous and cause both operation and safety problems if the issue is not monitored. The accumulation is caused by precipitation and marine icing spray under cold weather conditions. With significant amounts of ice build-up, the vessel's weight can increase dramatically. This problem can result in stability issues as the centre of gravity of the vessel may be altered. Figure 1 shows large amounts of ice on the Atlantic Kingfisher during the winter of 2006/2007. This type of accumulation can become a major hazard to the standard operations of the vessel. With the potential to capsize vessels, icing is a danger that must be monitored during the winter.



Figure 1: Icing event on the Kingfisher

2.1 Marine Icing Spray

Marine icing spray refers to large sprays of water onto the deck of the ship. It is caused by waves crashing into the hull of the ship under certain weather conditions. Marine icing spray, as shown in Figure 2, can produce large amounts of water on the vessel's deck, as the excess water will cause icing on susceptible areas of the vessel. High wind speed of approximately 9 m/s is needed to create sufficient waves (1m or higher) for the icing spray and a temperature of –10 °C is sufficient for icing to occur on the vessel. Under these conditions, marine icing spray is prone to create ice build-up and safety issues.



Figure 2: Splash occurred against the Kingfisher

3.0 Marine Icing Monitoring System

To monitor the icing events that occur on vessels, the Institute for Ocean Technology (IOT) developed the Marine Icing Monitoring System (MIMS). With the use of this technology, ice accumulation can be continuously observed to avoid problems that can occur during these circumstances.

MIMS technology is comprised of two cameras connected to a CPU (see Figure 3). The stationary cameras are located at the starboard and port sides of the vessel facing the front of the vessel. Each camera is programmed to take a picture in intervals of 12 minutes. The timing of both cameras is offset from each other creating one picture every 6 minutes. As well, the system includes a metal casing around the camera and a well-insulated area for all electronic components during marine conditions.

For monitoring purposes, a satellite phone was established to control the technology from IOT. The capabilities of the phone include zooming the camera

in and out and downloading images captured by the technology. Thumbnail images are often downloaded for monitoring since large full-scale images take great deal of time to produce. Instead, these images are retrieved from the vessel after the winter season.



Figure 3: MIMS cameras on the Caribou

The first Marine Icing Monitoring System was installed on Marine Atlantic's ferry, the MV Caribou. This system was used to gain information on the system's ability to tolerate the environmental conditions. From observations of the first cameras, additional heaters needed to be installed as the camera window continued to freeze during icing events. Adjustments were made to improve the second MIMS installed on the Atlantic Kingfisher. Visibility has increased from the first MIMS but some ice can still form on the camera window (shown in Figure 4). The images from the second MIMS are used for the automated analysis during the 2006/2007 winter. Currently, as of October 2007, these cameras have been moved to a similar oil supply vessel called the Atlantic Eagle. Seals, antenna, and power supply all needed to be replaced before installation.




Figure 4: Icing and precipitation on MIMS camera

4.0 Image Analysis

The images collected using the MIMS technology can be analyzed further to incorporate the amount and rate of ice accumulation during icing events. Python, an object-oriented programming language, is used for analysis in an automated approach. The program uses edge detection techniques to find the width of particular structures for each image during the icing event. By comparing these measurements to the actual width found with no ice, the computer can output the ice thickness. Currently, the analysis has been conducted for icing events occurring on the Atlantic Kingfisher in December 2006 – February 2007. The program incorporates positions from the fixed images of the Kingfisher, however, the method could be modified for other vessels in the future.

4.1 Positions

The positions for analysis have been chosen to correspond with the techniques used in the program. There are many factors that make one position more

suitable than another to analyze. For example, linear structures result in more accurate edge detection calculations than rounded or elliptical structures. This result is caused by the edge detection method chosen for analysis. The method focuses on pixels of the image in a linear approach causing rounded structures to be less accurate.

As well, positions with vertical members have ice accumulation that is more uniform than horizontal structures. During icing events, horizontal structures, such as the white railing shown in Figure 11, will create icicles. The analysis can become flawed at these positions as it becomes difficult to find ice thickness.

There have been 17 positions chosen for analysis during the icing events. As you can see from the figure below, the majority of which are located on the black pole structure. This structure appeared to give the most accurate results when computing the ice thickness on the vessel. With so many positions on this structure, relationships with respect to height and distance can be observed from analysis. As well, significant ice build-up has been observed on the black circular structures and the railing of the vessel in which three positions each have been analyzed.



Figure 5: Positions used during automated analysis

4.2 Image Processing

Each image in the icing event must undergo the same filters and enhancements to ensure the best possible results. When conducting image processing in Python, a new module called Python Imaging Library (PIL) must be imported into the script. PIL adds image-processing capabilities to your interpreter and contains all basic commands needed to manipulate your image. The commands are created to simplify programs and reduce the time it can take to run large self-written modules for images.

When the image is uploaded, it is rotated by a particular amount calculated for each position. This occurs so that the structure analyzed is in a vertical position required for edge detection. Next the image is changed completely to greyscale

(see Figure 6). A greyscale image is easier to process as all pixels in the image can be related using the same numerical scale (black = 0 and white = 255). After these processes, the program uses the crop command to focus on the position that is being calculated. The cropped image is modified to a size that will exclude as much noise and possible edges that can interfere. However, ice growth on the structure must be accounted for when determining a convenient size for the newly cropped image. This order of commands is created through testing of different configurations. The image has a greater clarity if the rotation and greyscale command precedes the cropping of the image.




Figure 6: (a) Icing image rotated (b) rotated and converted to greyscale

Following these modifications, the image undergoes enhancements to continue to make the image clear for processing. Auto contrast is one command that is used with a particular cut off level. Any greyscale pixel that is above or below the percentage used for cut off will be changed to black or white, respectively. Another important command is a Median Filter, used for reducing noise in the image. The program uses a 3x3 filter, which analyzes the pixels in that window size. The value of each pixel is examined and all pixels are changed to the median value of the area. This will help avoid speckle noise that can occur in the image. Other commands that can be used for noise reduction include smoothing or blurring the image as well as an EDGE_ENHANCE command to expose the edges better. However, from further tests, these commands were not included in

the script. These seemed ineffective or did not improve the calculated widths of the structure. The final image modification is a command known as FIND_EDGES. With this command, the image is converted to black and white as the greyscale pixels are changed to whichever extremity is closer. This results in a black image with edges surfacing as white pixels.

The image processing has changed slightly depending on the particular position during the calculation. For example, color can be a factor for the railing because it has a distinctive red color compared to the positions on the black structure. This creates a lighter image when the greyscale is incorporated. Therefore, changes have been made to create the most accurate results. Image processing for edge detection can be created with only a small amount of code with the use of Python Imaging Library. This module has made very technical processes into conveniently small commands for the script.




Figure 7: Generated image of the railing with image enhancements

4.3 Edge Detection

When the image has gone through the image processing steps, the program is ready to detect its edges. Images are comprised of pixels, single points in the

graphic image that occupy a definable area. Each pixel is represented in a numerical scale which can be anywhere between black at 0 or white at 255. The values of each column of pixels in the image are averaged and compiled in a table in an Excel spreadsheet for easy access. The program begins a loop process at the left side of the image and continues through each column until it has found the maximum value for half of the columns. The loop will end at this maximum and this pixel value is determined as the left edge of the structure. The same method is used for the right edge as the program checks from right to left of the image for the maximum. The subtraction of the right and left edges calculates the width of the structure in pixels.

4.4 Calibration

The width at each position analyzed has no significant meaning without any calibrations. The positions used have been manually measured on the Kingfisher vessel to use for this calibration process. The program is run through images with no ice accumulation to calculate the initial pixel width. The calibration factor of each position is equal to the actual width of structure (in centimetres) divided by the pixel width of the positions with no ice. This value will increase as positions are farther away from the camera. With a list of calibration factors multiplied by each position, respectively, the calculated widths can be displayed in centimetres. The ice accumulation can now be related in actual measurements that are suitable for the analysis.

4.5 Sub-Pixels

A problem that occurred after observing the analysis included frequent time intervals with the exact same width as the icing event progressed. This occurrence was not due to the lack of ice accumulation during these images. The problem is a result of the edge detection process whereby the calculated width can only be from one pixel to another (Ex. From the black structure each measurement is at least 0.68cm apart). The result is data that becomes fixed at

the same value for a period of time instead of steadily increasing data. To resolve this problem, the measured widths must be calculated in a sub-pixel level. The edge detection process discussed earlier needed small adjustments to achieve this goal. Instead of averaging pixel values of each column, you could use the same method numerous times with a selected amount of rows (used sections of 5 rows). By using the edge detection technique several times and averaging these values found, the data set becomes more accurate for the ice thickness analysis. The data shows an improved uniform increase as expected for actual conditions. As well, necessary error factors have been implemented to this list of edge values to ensure that flawed values do not affect the analysis.




Figure 8: Before sub-pixel method was incorporated into edge detection




Figure 9: After sub-pixel method incorporated

4.6 Generated Images

To assist with the analysis of the icing event, the program generates a progressive image to incorporate three stages of the image analysis. All three sections of the image are the cropped image at the particular position that is analyzed. The first section includes the image cropped and rotated while the second contains the image changed to greyscale with the other enhancements implemented by the program. Finally, the last section includes all edge commands and the final appearance that the edge detection will use for calculations. As well, the script produces lines as markers for the left and right edge of the structure. These appear on the first section as vertical lines for the linear structures and horizontal lines for the elliptical. These lines give an indication on whether the program is running properly and detecting the edges well. It also gives the ability to show the ice accumulation increase with each new

image. The images include reference number, time of day, and position number. Another property that has been included in the images is whether or not the detection process could not find an edge. If this is the case, the program will output 'Could not find edges' directly on the photo. This width value for the particular position is removed from the data. The indication creates further inspection and helps the detection process. Often you can reference back to the original image to check if any precipitation on the camera is the problem or if the process is not responding well.




Figure 10: Generated image of linear structure (black pole structure)

4.7 Elliptical Structures

The Edge detection method that has been used is ideally suited for linear structures such as black pole structure in the image. However, from inspection, there is significant ice accumulation on the circular black covers as shown in Figure 11. This accumulation warrants analysis at these positions. Three positions have been chosen to analyze with the program. Unfortunately, the techniques previously used for the linear structures do not accurately determine

the edges of the elliptical shape. To resolve this problem, the program has been adjusted with small changes to the edge detection. Instead of evaluating all rows of pixels, the program will average the pixel values of several rows in the middle of image. This will determine the rounded edge more effectively from the elliptical shape. This method works significantly better than the original, but the linear structures continue to show a more accurate result.




Figure 11: Generated image of the elliptical structure

5.0 Ice Progression Graph

With the addition of the matplotlib extension to Python, the program is given graphing capabilities to help display the ice analysis (see Appendix C). As shown in Figure 12, the script will output and save a graph displaying all the necessary calculations of the icing event in an organized manner (see Appendix B for additional graphs of each position during the December 29, 2006 icing event).




Figure 12: Graph generated from Dec. 29 icing event

5.1 Features

The graph includes a scattered plot of the width of each structure as the icing event progresses. A line of best fit is incorporated with respect to the data using standard commands in Python. The accuracy of this line is given in the top left corner of the graph as standard deviation. The residual standard deviation represents the average distance that each point is away from the best-fit line. As well, the ice thickness is calculated from the data by comparing the width of the standard structure with no ice and the icing width after the accumulation. The third calculation given at the top of the graph is the rate at which the ice is growing. This refers to the thickness of ice divided by the length of time for the icing event (five images are captured during one hour).

To increase the accuracy of the results, an error calculation is incorporated to avoid flawed data points (shown in Python Code, Appendix A). Edges that are not detected correctly can lead to a best-fit line that does not represent the entire data set well. By using the error formula, these points are removed from the data by comparing all points to the median value.

5.2 Relationships

From inspection of the graphs generated by the program, the most accurate data is retrieved from the black pole structure (see Appendix C for all positions). These positions have a smaller residual standard deviation than other position as the values are more closely related to the line of best fit. However, the horizontal pole of the black structure (positions 9, 10, and 11) does not calculate with the same accuracy. This is caused by the fact that some icicles have formed on the bottom of the pole creating ice build-up that is not uniform and difficult to calculate.

In addition to the black structure, the data from the railing positions were accurate with small deviation. However, more flawed values were removed and resulted in a smaller data set. These positions create better results than the elliptical data, as the computer often cannot detect the round edge effectively.

Another trend that can be observed from the data collected is with respect to the height and distance from the exterior of the vessel. As the height of the position decreases (seen in positions 1-4 and 5-8 of Figure 5), the ice accumulation increases. This occurrence is based on the marine icing spray as the lower positions of the structure tend to be sprayed in greater amounts. As well, the railing shows a relationship with the bow of the vessel. There is significantly greater ice accumulation the closer to the

bow since this is the part of the vessel, which the icing spray initially originates (positions 15, 16, and 17 of railing). Distance also plays a role with the white poles displayed in the image since they seem to be too far from the hull of the vessel to get sufficient icing spray to create accumulation.

6.0 Conclusion

The MIMS technology continues to be employed on the Atlantic Eagle as it captures a large amount of images during each winter. The images give the ability to monitor and research icing on offshore vessels and have the potential to avoid dangerous situations.

With the use of Python, ice accumulation and the rate of growth has been calculated in an automated approach. The accuracy of the automated analysis continues to improve and demonstrate the positions susceptible to icing. As MIMS and the detection methods develop, it can be a significant safety feature for vessels. Monitoring these icing events is necessary for all vessels travelling in waters that are prone to marine icing.

References

Guido van Rossum. *Python Tutorial*. February 21, 2008. http://docs.python.org/tut/tut.html>

Python Imaging Library. May 6, 2005. Handbook reference. Viewed January 2008. http://www.pythonware.com/library/pil/handbook/index.htm

Cluett, D. Automated Analysis of Marine Icing Images. Institute for Ocean Technology. 2007. SR-2007-02

Gibling, L. Marine Icing Events: an Analysis of Images Collected from the Marine Icing Monitoring system (MIMS) Institute for Ocean Technology. 2007 SR-2007-07

Appendix A

Python Code for Automated Image Analysis

```
import Image # PIL Python Image Library
import ImageOps
import ImageFilter
import ImageDraw
import ImageFont
import glob, os
import csv
from pylab import *
frame = 100000
calib = (0.68, 0.68, 0.68, 0.68, 0.68, 0.68, 0.68, 0.68, 0.68, 0.68,
boxS = (60, 80)
                # size of image segment
boxR = [12.6, 12.6, 12.6, 12.5, -9.5, -9.6, -9.6, -9.6, 94, 94, 94] #
rotation of image segment
boxO = [(575,350), (575,400), (575,575), (575,630),
        (950, 225), (950, 275), (950, 425), (950, 500),
        (725,1230), (725,1170), (725,1113)
        ] # location of corner of image segment after rotation
cmlist = [[] for i in range(len(boxR))]
boxesSize = [(a[0], a[1], a[0] + boxS[0], a[1] + boxS[1]) for a in box0]
holdSize = [ 0, 0 , boxS[0]*3, boxS[1]*len(boxO)] # output image qif
cnt = 1
fo = csv.writer(open("E:\Icing Event\icing.csv", 'wb'))
fof = csv.writer(open("E:\Icing Event\icingNum.csv", 'wb'))
col = [(' ')]*(3) # output data
for infile in glob.glob("E:\\Icing Event\\Icing Pics\\J*.jpg"):
    filepath, filename = os.path.split(infile)
    filename, ext = os.path.splitext(filename)
    results = [filename] # list of file names
    results.append(cnt) # append counter to list of file names
    im = Image.open(infile) # open image
    hold = im.crop(holdSize) # create image to hold visual results
    for i, box in enumerate(boxesSize): # for each area to analyze
        region = im.rotate(boxR[i], resample=2) # rotate image
        hold.paste(region.crop(box), (0, boxS[1]*i)) # save cropped
original
        #region = region.crop(box)
        region = ImageOps.grayscale(region)
        #region = region.filter(ImageFilter.SMOOTH)
        #region = region.convert('L')
        #region = region.filter(ImageFilter.BLUR)
        region = ImageOps.autocontrast(region, cutoff=10)
        region = region.filter(ImageFilter.MedianFilter(3))
        region = region.filter(ImageFilter.SMOOTH)
        region = ImageOps.autocontrast(region, cutoff=3)
        #region.show()
```

```
#edge = region.filter(ImageFilter.EDGE ENHANCE)
        edge = region.filter(ImageFilter.MedianFilter(3))
        edge = edge.filter(ImageFilter.FIND EDGES)
        edge = ImageOps.autocontrast(edge, cutoff=2)
        #edge.show()
        edge = edge.crop(box)
        hold.paste(region.crop(box),(boxS[0], boxS[1]*i)) # save
processed segment
        hold.paste(edge,(boxS[0]*2, boxS[1]*i)) # save edge segment
        width, height = edge.size # get the size of the image
        temp = [0]*width # temp list to hold average values
        string = ''
        data = list(edge.getdata()) # convert image to list of values
        first1 = []
        last1 = []
        for n in range(height/5):
            rge_htx = (0 + 5*n)
            rge_hty = (5 + 5*n)
            for j in range(width): # average values for each column
                for k in range(rge htx,rge hty):
                    temp[j] += float(data[k*width+j])
                temp[j] = temp[j]/(height/5)
                if i == 0: # for first segment output column averages
                    col[1] = j
                    col[2] = [\%5.1f' \% (temp[j])
                    col[0] = cnt
                    fo.writerow(col)
            peak = int(max(temp[5:-5])*0.7) # define peak value as 70%
of max
            for k in range(5, width/2): # find left edge
                if peak < temp[k]:</pre>
                    first1.append(k-1)
                    break
            for k in range(width-5, width/2, -1): # find right edge
                if peak < temp[k]:
                    last1.append(k+1)
                    break
##
          print first1, last1
        if len(first1) != 0 and len(last1) != 0:
            error = (first1 - mean(first1))**2
            ermedian = median(error) * 1.5
            q = 0
            for f in range(0,len(first1)):
                if error[f] > ermedian:
                    first1 = delete(first1, [g])
                    g = g-1
                elif error[f] < ermedian/2.5:</pre>
                    first1 = delete(first1, [q])
```

```
g = g-1
                g += 1
            error = (last1 - mean(last1))**2
            ermedian = median(error) * 1.5
            q = 0
            for f in range(0,len(last1)):
                if error[f] > ermedian:
                    last1 = delete(last1, [g])
                    q = q-1
                elif error[f] < ermedian/2.5:</pre>
                    last1 = delete(last1, [q])
                    g = g-1
                q += 1
        first = mean(first1)
        last = mean(last1)
##
          print first1,last1
##
          print first, last
        pixelwidth = (last-first)
        draw = ImageDraw.Draw(hold)
        cmwidth = calib[i] * pixelwidth
        if len(first1) == 0 or len(last1) == 0:
            draw.text((5, boxS[1]*i+20), 'Could not find edges')
            cmlist[i].append(cmwidth)
        results.append(pixelwidth) # append width of edges to results
        text = ' %s , %3d, %3d, %3d' % (filename, pixelwidth, int(first),
int(last))
        string = '%2.1f' % (cmwidth) + 'cm'
        pos = (int(boxS[0]/3), int(boxS[1]*i+boxS[1]/2)-1)
        draw.text( pos, string) # write edge width on image
        topline = int(boxS[1]/3+boxS[1]*i)
        botline1 = int(boxS[1] *2/3 + boxS[1] *i)
        botline2 = int(boxS[1]+boxS[1]*i)
        draw.line(((first,boxS[1]*i), (first,topline)),fill=256,width=1)
        draw.line(((first,botline1), (first,
botline2)),fill=256,width=1)
        draw.line(((last,boxS[1]*i),(last,topline)),fill=256,width=1)
        draw.line(((last,botline1),(last,botline2)),fill=256,width=1)
# displays text for position counter, image counter, and time of each
image
        for h in range(0,len(boxR)):
            string1 = (('%d' % (h+1)), ('%d' % (cnt)), (infile[-9:-5]))
            pos = ((5, boxS[1]*h+70), (4,5), (20,5))
            for q in range(0,len(string1)):
                draw = ImageDraw.Draw(hold)
                draw.text(pos[g], string1[g])
            g += 1
        h += 1
```


```
print text, cnt # output to screen
    fof.writerow(results) # write results to second file
    picture = 'E:\Icing Event\\Analysis Pics\\'
    frame += 1
    string = '%s' % (frame)
    pic = '%s%s.gif' % (picture, string[-4:] )
    hold.save(pic[0:len(picture)] + 'jan15pole' + pic[-8:], "GIF")
    cnt +=1
                    # exit after first file
    if cnt >= 40:
        break
for j in range(len(cmlist)):
    x_list = arange(0,len(cmlist[j]))
    y^{-}list = []
    for x in x list:
        y = cm\overline{list[j]}[x]
        y list.append(y)
    y_list = array(y_list)
    m,b = polyfit(x_list,y_list,1)
    error = (y_list - (m*x_list + b))**2
    ermedian = median(error) * 10
    q = 0
    for i in range(0,len(y list)):
        if error[i] > ermedian:
            #del y_list[i]
            y_list = delete(y_list, [g])
            g = g-1
        elif error[i] < ermedian/100:</pre>
            y_list = delete(y_list, [g])
            g = g-1
        q += 1
    x_list = arange(len(y_list))
    m,b = polyfit(x list,y list,1)
    error = (y_list - (m*x list + b))**2
    ermedian = median(error) * 5
##
      print error
##
      print ermedian
     print y_list
print len(y_list)
##
##
    g = 0
    for i in range(0,len(y_list)):
        if error[i] > ermedian:
            #del y_list[i]
            y list = delete(y list, [g])
            g = g-1
        elif error[i] < ermedian/25:</pre>
            y_list = delete(y_list, [g])
            g = g-1
```


```
g += 1
    x list = arange(len(y list))
    m,b = polyfit(x list,y list,1)
    bestfit = m*x list + b
    ice thick = (max(bestfit) - min(bestfit))/2
    string = '%s' % (j+1)
    stringice = '%1.2f' % (ice thick)
    icerate = (max(bestfit) - min(bestfit))/(cnt/5)
    stringrate = '%1.3f' % (icerate)
   print 'The ice thickness for Position', string, 'is', stringice,
'cm'
   print 'The rate of ice thickness is ', stringrate, 'cm/hr'
    std_ice = array((y_list - bestfit)**2)
    std_value = sqrt((std_ice.sum())/(len(y_list)-2))
    std str = '%1.2f' % (std value)
    print std value
   plot(x_list, y_list, 'bo', x_list, bestfit, '-k', linewidth=2)
string = '%s' % (j+1)
    title('Ice Progression for Position ' + string + ' of Image (Jan
15)')
   xlabel('Time Progress')
    ylabel('Width (cm)')
    figtext(0.15,0.825, 'Ice Thickness = ' + stringice + ' cm',
color='red')
    figtext(0.15,0.725, 'Standard Deviation = ' + std_str, color='red')
    figtext(0.15,0.775, 'Rate of Increase = ' + stringrate + ' cm/hr',
color='red')
    savefig('E:\\Icing Event\\Figures\\jan15figposition' + string +
'.png')
   clf()
```


Appendix B


Sample Analysis Pictures for Icing Event (Dec. 29, 2006)


Positions 1 – 11
















Positions 12 – 14
















Positions 15 – 17





















Appendix C


Icing Event Figures for Ice Accumulation

















































National Research Council Canada

Institute for Ocean Technology

Conseil national de recherches Canada

Institut des technologies océaniques

Thermal Regulation Manikin Support Frame

SR-2008-05

Ron Ryan

April 2008

DOCUMENTATION PAGE

REPORT NUMBER	NRC REPORT NUMBER	DATE			
SR-2008-05		April 200	8		
REPORT SECURITY CLASSIFICATION			DISTRIBUTION		
Unclassified		Unlimited			
TITLE			<u>, </u>		
Thormal Degulation Manikin Support Frame					
Thermal Regulation Manikin Support Frame AUTHOR(S)					
Ron Ryan					
CORPORATE AUTHOR(S)/PERFORMING AGENCY(S)					
Institute for Ocean Technology, National Research Council, St. John's, NL					
PUBLICATION					
N/A					
SPONSORING AGENCY(S)					
IOT					
IOT PROJECT NUMBER		NRC FILE NUMBER			
42_2264_16 KEY WORDS PAGES FIGS. TABLES					
Manikin, 42_2264_16, Support Frame		53	11	4 (App)	
SUMMARY					
The project concerns the design of a support frame to assist in the buoyancy of the thermal manikin while in an immersion suit in water. The support frame will allow the manikin to be positioned so that it mimics a human position while in an immersion suit in water.					
Arctic Avenue St. John's, NL	cean Technology e, P. O. Box 12093				

Summary

The purpose of this report is to describe the design of a thermal regulation manikin support frame. The "Human Thermal Regulation in Wind and Waves" project was set forth due to Transport Canada requiring immersion suits be regulated and certified. The Canadian General Standards Board set the following criteria: Prevent a 2 degrees Celsius drop in core body temperature in 2 degrees Celsius water over 6 hours. Human subjects along with a thermal manikin will be used to test the immersion suits. The immersion suits orientate the human body in a particular way that the manikin is unable to accomplish. This leads to the design of a support frame that will orientate the manikin properly. The support frame has four sections with adjustability being a key feature in the design. There is the outer and inner frame, the outer to inner frame connectors, and the manikin supports. The outer frame is removable to allow the use of the inner frame to fit in the calorimeter tank. The inner frame has a wide range of orientations due to the outer to inner frame connectors. The thermal manikin is suspended in the manikin supports using nylon straps that are adjustable. Five connecting points secure the manikin, which there is one at the chest, two at the thighs, and two at the ankles. Buoyancy calculations were preformed for the pre "as fabricated" frame only and not with the manikin where it would have been too time consuming to create an accurate CAD model. Based on the calculations the frame would require the assistance of foam to be neutrally buoyant at the desired water line. It is necessary to test immersion suits so that they can be used for survival in the ocean.

Table of Contents

Introduction	2
Design Criteria	2
The Concept	3
The Design	3
Outer Frame	4
Outer to Inner Connection	5
Inner Frame	6
Manikin Supports	7
Design Analysis Description and Results	8
Final Design Description	9
Conclusion and Recommendations	11
Appendix A: Calculations	12
Appendix B: Fabrication Drawings	15
Appendix D: Materials/Pricing	49
Table of Figures	
Figure 1: Floating Support Frame	3
Figure 2: Outer Frame with Floats	
Figure 3: Outer Frame Elbow with Screws	4
Figure 4: Primary Connection	5
Figure 5: Secondary Connector	6
Figure 6: Inner Frame	7
Figure 7: Inner Frame Connection	7
Figure 8: Manikin Support	8
Figure 9: Manikin out of Water	9
Figure 10: Manikin in Water	10
Figure 11: Manikin in Immersion Suite	10

Introduction

The floating support frame design was developed as part of the project 42_2264_16, "Human Thermal Regulation in Wind and Waves". Due to Transport Canada regulations it is required that immersion suits be tested in calm and circulating water so that they can be certified and approved for real life survival situations. In order to gain approval certain criteria has to be met such that the immersion suit must prevent a drop of 2 degrees Celsius from the original core body temperature, in 2 degrees Celsius water in about 6 hours. To test these suits human subjects are needed along with the use of a thermal manikin that can be heated by internal heaters in different areas of its body. This testing of the suits with the thermal manikin will provide valuable information such as how much energy is needed to maintain the manikin's body temperature. The immersion suit allows the human body to float in a particular orientation that the thermal manikin would not be able to imitate. This circumstance made necessary the design of a floating support frame that will position the manikin similar to that of the human's orientation while in an immersion suit. The floating support frame will allow the thermal manikin to be configured in different physical orientations, such as lying flat or even in a sitting position depending on the protective clothing being tested. The frame is manly designed for "NEMO" a thermal regulation manikin however it should work with other manikins.

Design Criteria

Below is a list of design criteria for the design of the support frame.

- Highly adjustable
- NEMO's weight of 155 lbs
- NEMO's height of 5'9"
- Support for other manikins
- Simple design
- Minimal fabrication
- Cost effective
- Light weight as well as rigid
- Mooring locations
- Operation in wind and waves environment
- Fit into Calorimeter Tank (7' X 4')

The Concept

There are two frames, an inner and outer frame. The inner frame will support the manikin and the outer frame will provide buoyancy adjustment and some stability. The connection from the outer frame to the inner frame will allow the inner frame to be at some angle with respect to the outer frame. The inner frame would have a hinge approximately half way so that the upper section could be at some angle with respect to the lower section, this will allow the manikin to lie flat or sit up. There are 5 supporting points from above and below the manikin, 2 at the ankles, 2 at the thighs, and 1 at the chest. Nylon straps will be used to connect the manikin to the frame and the straps will be adjustable so the desired freeboards can be obtained. Also note that nylon straps are non-conductive, and have a small contact area with the manikin so the results of the test will not be affected. Also outer frame will be able to separate from the inner frame to allow the inner frame to fit in a calorimeter tank. The main material used is PVC with a small amount of Aluminum for connections.

The Design

Figure 1 shows the complete frame that is broken down into 4 sub components, which will be discussed separately.




Figure 1: Floating Support Frame

Outer Frame

The outer frame in Figure 2 is made of 1-1/4 inch Schedule 80 PVC pipe. The PVC elbows in figure 3 are connected with screws to easily disconnect the members for the addition of foam or weight to the outer frame from ether corner. The outer frame was filled with expanding foam to fill the cavity so sealing is not an issue which also provides a positive buoyant force to assist in supporting the inner frame and the manikin.




Figure 2: Outer Frame with Floats




Figure 3: Outer Frame Elbow with Screws

Outer to Inner Connection

There are primary and secondary connections between the inner and outer frames. The primary connection is made from multiple sizes and connectors of PVC. There is a 1-1/2 inch Schedule 40 pipe in a 2 inch Schedule 80 pipe with 4 slits to allow a compressive force created by a pipe clamp (not shown in figure) to prevent the two from rotating. The 2 inch pipe is connected to a 2 inch Tee connector that is split to allow it to be removed. Also the 1-1/2 inch pipe is fixed to a 2 to 1-1/2 inch reducing Tee connector, which is also split (see figure 4). A spacer is needed to connect the reducing Tee to the outer frame, which is a small diameter. This connection allows the inner and outer frames to be connected together so the outer frame can support the inner frame, but will also allow the inner frame to be adjusted in different orientations. The primary connector is able to translate along both the inner and outer frame depending on the position of the manikin and allow the two frames to be at different angles. The secondary connection is made up of PVC and Aluminum. In figure 5 there are two aluminum bars that are connected together and the ends are connected to a 2 inch PVC Tee connector. One end connects to the inner frame and the other connects to the outer frame with the same spacer as the primary connector to connect to the outer frame. The secondary connector will reinforce the position of the two frames and remove a moment on the primary connector.




Figure 4: Primary Connection




Figure 5: Secondary Connector

Inner Frame

The inner frame is made primarily of 2 inch schedule 40 PVC pipe with 90° elbows. The elbows attached to the pipe with PVC cement rather than with screws like the outer frame. As illustrated in figure 6 there is an upper section and a lower section. The upper section is where the upper portion of the manikin such as head and chest would be placed and the lower is where lower portion of the manikin will be placed. The manikin supports will be connected to the sides of the inner frame. The upper frame is connected to the lower frame using an aluminum connection elbow as show in figure 7. This connection elbow allows the upper and lower sections to be set at certain angle with respect to one another. The angle can range from 0 to 130 degrees by the use of a slot with a locking bolt (not shown in figure). The upper section of the connection is fixed while the lower is movable. The inner frame was filled with expanding foam to assist in buoyancy and to also prevent internal water sloshing during a test in waves that might possibly affect frame motion.




Figure 6: Inner Frame



Figure 7: Inner Frame Connection

Manikin Supports

There are three identical manikin supports as shown in figure 8. *These are used* to support the chest area, the thigh area and the ankles respectively and are made from a number of different sizes of PVC pipe. The top and bottom beams are 2 inch PVC schedule 40 pipe with 90° elbows. There is a 2 inch schedule 80 pipe that fits over a 1-1/2 inch schedule 40 pipe allowing it to be telescopic so that the length can be adjusted. There is a 2 to 1-1/2 inch reducer to connect the inner pipe of the telescopic section. A split 2 inch PVC cross is used to attach the manikin supports to the inner frame using clamps (not shown in figure). This also allows the manikin supports to be translated along the inner frame, flipped or removed. The manikin supports were also filled with expanding foam for the same reasons as the inner frame. There are 5 main manikin connecting points, one at the chest, two at the thighs and two at the ankles. Ultra abrasion-resistant nylon straps will be used to connect the manikin support frame to the manikin at these five locations. The manikin connection points will be suspended between

the top and bottom beams of the manikin supports. Nylon is used because it is a non conductive material, non abrasive and easy to work with. The straps are secured to the top and bottom beams using clamps, which will allow the straps to be adjusted up or down, or transversely depending on the freeboard requirements or manikin orientation.




Figure 8: Manikin Support

Design Analysis Description and Results

The basic design calculations were completed by hand and are provided in Appendix A. The NEMO manikin weighs approximately 155 lbs (70 kg) dry and its weight distribution is unknown so an estimate was used. During fabrication the top and bottom cross beams of the manikin supports were tested for deflection by applying a load and then visually inspect the part. The top beam of the manikin support was loaded to 176 lbs (80 kg), which is more than required since there are three manikin support frames so the weight would be distributed. The 2 inch PVC pipe is rated by the manufacture to withstand a maximum pressure of 300 psi so failure would most likely occur at the clamps or cemented joints. The nylon straps have a breaking strength of 2500 lbs so there is no concern with the straps breaking.

Final Design Description

The design was tested in the trim tank in the machine shop. The frame was able to support the weight of the manikin while out of the water (see figure 9) and in the water. With no immersion suit on the manikin, floats were needed to support the manikin at the proper level (see figure 10). However, with the immersion suit on there was sufficient additional buoyancy such that the outer frame was no longer required since it was providing too much buoyancy. As a result the outer frame was removed and two 5 kg weights were attached to the lower section of the chest manikin support to help combat the excess buoyancy of the immersion suit. This configuration is shown in figure 11.



Figure 9: Manikin out of Water




Figure 10: Manikin in Water



Figure 11: Manikin in Immersion Suit

Conclusion and Recommendations

It is imperative to test immersion suits or other survival gear so that we know and understand how well they work, particularly with respect to energy (heat) loss in realistic operations. The NEMO manikin is a very important sophisticated piece of equipment that will allow us to study the suits and determine how much energy is lost and determine the thermal resistance of the immersion suit or survival gear. Tank Tests will help to determine how long a person can survive in the immersion suite and the floating support frame, designed to hold the manikin in a natural human orientation while in an immersion suit is an important apparatus in ensuring accurate test results. The support frame preformed as expected. One possible improvement would be to allow easier adjustment of the straps.

Appendix A: Calculations

Equations:

The calculations preformed were for the pre as fabricated design.

$$F_{buoyanoy} = \rho V g$$

$$F_{net} = mg - \rho Vg$$

Density of materials:

Water =
$$1000^{kg} J_{ox}^{3}$$

Inner Sections =
$$1672.17 \frac{kg}{m^3}$$

Outer Frame Filled =
$$1390 \frac{kg}{m^3}$$

Styrofoam =
$$48.05^{kg}$$
/_{m³}

Inner Sections (IS) at water line:

$$V = 0.009306m^3$$

$$m = 27.39kg$$

$$F_{net(65)} = 27.39 kg \times 9.81 \frac{m}{s^2} - 1000 \frac{kg}{m^3} \times 0.009306 m^3 \times 9.81 \frac{m}{s^2} = 177.4N$$

Outer Frame Filled (OFF) at water line:

$$V = 0.005271m^3$$

$$m = 7.33kg$$

$$F_{netQFF} = 7.33kg \times 9.81 \frac{m}{s^2} - 1000 \frac{kg}{m^2} \times 0.005271 m^2 \times 9.81 \frac{m}{s^2} = 20.2N$$

Clamps:

$$V = 0.000214m^3$$

$$m = 2.70kg$$

$$F_{net(Clamps)} = 2.78kg \times 9.81^{m}_{s^2} - 1000^{kg}_{m^3} \times 0.000214m^3 \times 9.81^{m}_{s^2} = 25.17N$$

Total:

$$F_{net\ (Clamps)} = F_{net\ (S)} + F_{net\ (Clamps)} + F_{net\ (Clamps)} = 177.4N + 20.2N + 25.17N = 222.7N$$

Foam required:

Through iteration the volume of foam determined to cause the frame to be neutrally buoyant at the water level is $V=0.025114m^3$


$$m = 2.41kg$$


$$F_{netGoam} = 2.41 kg \times 9.81 \, m_{/s^2} - 1000 \, kg_{/m^2} \times 0.025114 m^2 \times 9.81 \, m_{/s^2} = -222.7 N$$


Result:


$$F_{net \text{ (Result)}} = F_{net \text{ (total)}} + F_{net \text{ (Foam)}} = 222.7N - (-222.7N) = 0N$$


Appendix B: Fabrication Drawings




























































































Appendix D: Materials/Pricing

*	National Research Council Canada
	Institute for Ocean

Institute for Ocean Technology

Conseil National de Recherches

Institut des Technologies Océaniques

To be Assigned by Finance & Supply Order Number:

IMPORTANT:

This number must appear on invoices, B/L, packing lists, correspondence and

		outside containers.			
Project Code or Name: Start Date (If Services):			Place ox 12093 Station A	Place Kerwin C.P. 12093 Station postale A	
Completion or Date Req'd:	11-Feb-08		n's Newfoundland	St-Jean, Terre-Neuve	
Supplier: Mcmaster-Carr Address:	Mcmaster-Carr	A1B 3T Fax: (70	5 09) 772-2462	A1B 3T5 Telecopieur: (709) 772-2462	
		IOT is located on Me	IOT is located on Memorial University's campus on Sandpits Rd. off Arctic Av (between the Engineering Building and the smoke stack). Deliveries are only		
Telephone:				m - 1:00pm and 1:30pm - 4:30pm	
Contact:			Monday to Frid	day.	
Fax:		Ship Via:			

Item #	Part #	Description	Unit of Issue	Quantity	Unit Cost	Total Cost
1	48855K14	1 1/4" sch 80 PVC pipe, 10' lth	ea	4	\$ 9.82	\$39.28
2	48855K26	2 " sch 80 PVC pipe, 5' Ith	ea	2	\$ 10.74	\$21.48
3	48925K15	1 1/4" sch 80 PVC elbow	ea	5	\$ 3.00	\$15.00
4	48925K16	1 1/2" sch 40 PVC pipe, 10' lth	ea	2	\$ 8.23	\$16.46
5	48925K19	2" sch 40 PVC pipe, 10' lth	ea	7	\$ 11.03	\$77.2
6	4880K246	2 1/2" sch 40 PVC pipe, 10' lth	ea	2	\$ 22.04	\$44.08
7	4880K978	2" sch 40 PVC cross	ea	8	\$ 5.34	\$42.72
8	4880K26	2" x 1 1/2" sch 40 PVC reducing tee	ea	3	\$ 2.42	\$7.20
9	5415K22	2" sch 40 PVC elbow	ea	18	\$ 1.83	\$32.94
10	3439T11	Band clamp, 3", pk of 10	pk	6	\$ 8.10	\$48.60
11	29705T86	1" nylon webbing	ft	400	\$ 0.60	\$240.00
12	2974T46	Plastic buckle, pk of 10	ea	2	\$ 6.29	\$12.58
13	8975K438	Plastic plate, pk of 25	ea	2	\$ 5.45	\$10.90
14	8975K438	Aluminum bar, 1/4"x 6", 2' lth	ea	1	\$ 38.08	\$38.08
15	92001A339	3/8"-16 ss wing nut, pk of 10	pk	1	\$ 8.15	\$8.1!
16	91841A035	3/8"-16 ss nut, pk of 50	pk	1	\$ 14.64	\$14.64
17	92198A634	3/8"-16 x 2 1/2" ss shcs, pk of 10	pk	1	\$ 8.99	\$8.99
18	92240A622	3/8"-16 x 3/4" ss shcs, pk of 25	pk	1	\$ 11.20	\$11.20
19	5415K37	Band clamp, 6.5", pk of 10	pk	1	\$ 12.55	\$12.55
20	5415K38	Band clamp, 7", pk of 10	pk	1	\$ 12.70	\$12.70
21	5415K43	Band clamp, 10", pk of 5	pk	1	\$ 8.34	\$8.34
22	5415K44	Band clamp, 12.25", pk of 5	pk	1	\$ 8.27	\$8.27
23	48855K24	1 1/4" sch 80 PVC pipe, 5' lth	ea	4	\$ 7.37	\$29.48
		Mastercard				
		5569 0999 9860 9063				
		Exp 05/09				
		Authorization #				
Receivi	 ing Inspection Leve	el: ☑A ☐B ☐C ☐D ☐Special			Sub-Tota	\$760.9
	Confirmed Orde	er: 🗸 Yes 🗌 No			Freight	\$100.00
Taxe	es Incl. in Sub-Tota				Tax Rate	
	ht Incl. in Sub-Tota				Taxes	
					Total	

Special Instructions:

- If a Level D inspection is identified above, this means that IOT and/or its client will be inspecting the goods at the vendor's site. If appropriate
- info is not included with this form, please contact the undersigned.
- When specified, please provide certification, e.g. Mill Certificate, Calibration Certificate or MSDS.
- IOT reserves the right to refuse all orders that do not contain packing slips/invoices and/or do not make reference to the Order Number specified above.
- This document contains the following attachments or references (e.g. drawing numbers):

Notes/Remarks:

PRICES LISTD IN US DOLLARS Order Confirmation # 0202SREID

Requested by: Scott Reid	Date:	2-Feb-07
Approved by:	Date:	

.de.	National Research Council
T	Canada

Institute for Ocean Technology Conseil National de Recherches Canada

Institut des Technologies Océaniques

To be Assigned by Finance & Supply Order Number:

IMPORTANT:

This number must appear on invoices, B/L, packing lists, correspondence and outside containers.

		outside contai	ners.
Project Code or Name: 42_Start Date (If Services): Completion or Date Req'd: 22-Supplier: More Address: Telephone: Contact:	Feb-08	Ship To: Kerwin Place P.O. Box 12093 Postal Station A St. John's Newfoundland A1B 3T5 Fax: (709) 772-2462 IOT is located on Memorial Universitys cam (between the Engineering Building and the accepted at Door Number 3 between 8:30ar Monday to Fri	smoke stack). Deliveries are only m - 1:00pm and 1:30pm - 4:30pm
Fax:		Ship Via:	

Item #	Part #	Description	Unit of Issue	Quantity	Unit Cost	Total Cost
1	2389K73	2" x 1 1/2" reducing coupling, PVC	ea	8	\$ 1.91	\$15.28
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
		Mastercard				
		5569 0999 9860 9063				
		Exp 05/09				
		Authorization #				
Receivi	ing Inspection Level:				Sub-Total	\$15.28
	Confirmed Order:				Freight	\$15.00
Taxe	es Incl. in Sub-Total:	☐ Yes ☑ No ☐ N/A			Tax Rate	13%
Freigl	ht Incl. in Sub-Total:	✓ Yes			Taxes	\$3.94
_					Total	\$34.22

Special Instructions:

- If a Level D inspection is identified above, this means that IOT and/or its client will be inspecting the goods at the vendor's site. If appropriate info is not included with this form, please contact the undersigned.
- When specified, please provide certification, e.g. Mill Certificate, Calibration Certificate or MSDS.
- 3 IOT reserves the right to refuse all orders that do not contain packing slips/invoices and/or do not make reference to the Order Number specified above.
- This document contains the following attachments or references (e.g. drawing numbers):

Notes/Remarks:

PRICES LISTD IN US DOLLARS Order Confirmation # 0214SREID

Requested by: Scott Reid	Date:	22-Feb-07
Approved by:	Date:	

*	National Research Council Canada

Institute for Ocean Technology Conseil National de Recherches Canada

Institut des Technologies Océaniques

To be Assigned by Finance & Supply Order Number:

IMPORTANT:

This number must appear on invoices, B/L, packing lists, correspondence and outside containers.

	outside containers.
Project Code or Name: 42_2264_16 Start Date (If Services):	Ship To: Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093 Postal Station A Station postale A
Completion or Date Req'd: 22-Feb-08	St. John's Newfoundland St-Jean, Terre-Neuve
Supplier: Mcmaster-Carr	A1B 3T5 A1B 3T5 Fax:(709) 772-2462 Telecopieur: (709) 772-2462
Address:	IOT is located on Memorial University's campus on Sandpits Rd. off Arctic Ave (between the Engineering Building and the smoke stack). Deliveries are only
Telephone:	accepted at Door Number 3 between 8:30am - 1:00pm and 1:30pm - 4:30pm
Contact:	Monday to Friday.
Fax:	Ship Via:

Item #	Part #	Description	Unit of Issue	Quantity	Unit Cost	Total Cost
1	4880K246	2" sch 40 Cross, PVC	ea	4	\$ 5.34	\$21.36
2	4881K24	1 1/4" sch 80 elbow, PVC	ea	4	\$ 3.00	\$12.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.0
						\$0.0
						\$0.0
						\$0.00
		Mastercard				
		5569 0999 9860 9063				
		Exp 05/09				
		Authorization #				
Receiv	 ing Inspection Lev	el: ☑A ☐B ☐C ☐D ☐Special			Sub-Total	\$33.36
ROCCIV	Confirmed Ord				Freight	\$20.00
Tav	es Incl. in Sub-Tot				Tax Rate	13%
					-	
Freig	ht Incl. in Sub-Tot	di. Ľites ∐NO ∐N/A			Taxes	\$6.94
					Total	\$60.3

Special Instructions:

- If a Level D inspection is identified above, this means that IOT and/or its client will be inspecting the goods at the vendor's site. If appropriate info is not included with this form, please contact the undersigned.
- When specified, please provide certification, e.g. Mill Certificate, Calibration Certificate or MSDS.
- 10T reserves the right to refuse all orders that do not contain packing slips/invoices and/or do not make reference to the Order Number specified above.
- This document contains the following attachments or references (e.g. drawing numbers):

Notes/Remarks:

PRICES LISTD IN US DOLLARS Order Confirmation # 0221SREID

Requested by: Scott Reid	Date:	22-Feb-07
Approved by:	Date:	

*	National Research Counc Canada	il Conseil National de Recherches Canada	To be Assigned by Finance & Supply					
	Institute for Ocean Technology	Institut des Technologies Océaniques	Order Number: IMPORTANT: This number must appear on invoices, B/L, packing lists, correspor outside containers.			sts, correspondence and		
	oject Code or Name: rt Date (If Services):		Ship To: Kerwin Place P.O. Box 12093			Place Kerwin C.P. 12093		
Completion or Date Req'd: 29-Feb-08			Postal Station A Station postale A St. John's Newfoundland St-Jean, Terre-N A1B 3T5 A1B 3T5					
	Supplier:	RDM Industrial	A1	5 pieur: (709) 772-2462				
	Address:	799 Water St., St. John's	IOT is located on Memorial University's campus on Sandpits Rd. off Arcti					
	Telephone:	726-7690	(between the Engineering Building and the smoke stack). Deliveries are accepted at Door Number 3 between 8:30am - 1:00pm and 1:30pm - 4:					
Contact: M		Margie O'Dea	Monday to Friday.					
	Fax:	726-7696	Ship Via:	Ship Via:				
Item #	Part #	Description	Unit of Issue	Quantity	Unit Co	ost	Total Cost	
1	STA-38X4	3/8"-16 x 4" hex head bolt, ss	ea	20	\$	1.08	\$21.60	
2	STA-CB38X2	3/8"-16 x 2" carriage holt ss	ea	4	\$	ი გ5	\$3.4	

Item #	Part #	Description	Issue	Quantity	Unit Cost	Total Cost
1	STA-38X4	3/8"-16 x 4" hex head bolt, ss	ea	20	\$ 1.08	\$21.60
2	STA-CB38X2	3/8"-16 x 2" carriage bolt, ss	ea	4	\$ 0.85	\$3.40
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
						\$0.00
		Mastercard				\$0.00
		5569 0999 9860 9063				\$0.00
		Exp 05/09				\$0.00
		Authorization # 125535				\$0.00
						\$0.00
Receiving Inspection Level:					Sub-Total	\$25.00
	Confirmed Orde				Freight	
Taxes Incl. in Sub-Total: ☐ Yes ☑ No ☐ N/A					Tax Rate	13%
Freight Incl. in Sub-Total: ☑ Yes ☐ No ☐ N/A					Taxes	\$3.25
					Total	\$28.25

Special Instructions:

- If a Level D inspection is identified above, this means that IOT and/or its client will be inspecting the goods at the vendor's site. If appropriate info is not included with this form, please contact the undersigned.
- When specified, please provide certification, e.g. Mill Certificate, Calibration Certificate or MSDS.
- 3 IOT reserves the right to refuse all orders that do not contain packing slips/invoices and/or do not make reference to the Order Number specified above.
 - This document contains the following attachments or references (e.g. drawing numbers):

Notes/Remarks:

REFERENCE # 29_02_SREID_03

Requested by: Scott Reid	Date:	29-Feb-08
Approved by:	Date:	